PROJECT REPRESENTATIVE'S DAILY REPORT

Pg. 1 **Report No**. 106

Date: 2015-01-21 **Day**: Wednesday

Architect: Kang Associates

Project: Renovation and Addition to Tewksbury Town Hall

OPM: CBI Consulting Inc. **Clerk of the Works**: Jeff Barnes

Contractor: G.V.W., Inc.

 Weather:
 7:30 am:
 clear
 Noon:
 partly sunny
 3:00 pm:
 cloudy

 Temperature:
 7:30 am:
 18°
 Noon:
 28°
 3:00 pm:
 31°

Superintendent: Vinnie Bomal

PERSONNEL COUNT	Spec Section	Contractor	Trade	Foreman	Journeymen	Helpers	Total
General Contractor:	Div. 06	GVW	Carpentry	2	5	1	8
	Div. 04		Masonry	1	0	0	1
	09 90 00		Painting	0	0	0	0
	02 41 19		Demolition 1	1	0	2	3
	Div. 31		Site Work	1	0	0	0
	01 50 00		Temp. Facility	0	0	0	0
				0	0	0	-
	Div. 05		Misc. Metals	U	0	0	0
	Div. 03		Concrete	1	4	0	5
Subcontractors:	02 08 00	A & J Demo Services	Abatement	0	0	0	0
	26 00 00	Griffin Electric	Electrical	0	0	0	0
	22 00 00	Lapan Mechanical	Plumbing	0	0	0	0
	07 31 00 07 53 00 07 61 19	Meadows Construction	Roofing	0	0	0	0
	Div. 23	Ambient Temp. Corp.	HVAC	1	0	1	2
	Div. 21	Encore Fire Protection	Fire Suppression	0	0	0	0
Total:				6	9	4	19

DAILY REPORT

Activities Today:

- 1) Mason: making masonry opening in wall on 2nd floor
- 2) <u>Demo/Labor</u>: general site cleaning; assisting other trades
- 3) Carpenter: continuing with boxing around bases of posts; continuing to lay out walls; continuing with framing stair #3; installing soffit and vent on the south side of the meeting hall
- 4) HVAC: continuing with ductwork and equipment installation in the attic and 1st floor
- 5) Concrete: continuing with erecting formwork for addition at the stepped footings for the south wall of the addition

Copies to: Richard Montuori, Town of Tewksbury

Ed Johnson, Town of Tewksbury

Steve Sadwick, Town of Tewksbury

Wayne Lawson, CBI

Jenne dos Santos, CBI Kaffee Kang, Kang Architects

Jennifer Pincus, Kang Architects

Bob Harukewicz, GVW Inc.

PHOTO INDEX



Photo showing carpenters installing a window on the east elevation at the north stairwell.



Bird's eye photo showing the blocking being installed at a post base in the meeting hall.



Photo showing carpenters installing soffit and soffit vent along the south elevation of the meeting hall.



Photo showing HVAC mechanic installing equipment in the attic at the east elevation of the main building.



Photo showing ductwork and equipment installed in the attic.



Photo showing HVAC equipment installed in the south wing.



Photo showing HVAC equipment installed beneath the 2nd floor build-out.



Photo showing mason installing a lintel for a new masonry opening on the 2^{nd} floor.



Photo showing formwork being installed for the south wall of the addition.



Photo showing the formwork looking east.